



Battery Side:
Red: + Main Positive
Plug into RS485
Black: - Main Negative

Gauge Side:

Red: V+
Green: B
Yellow: 3
Black: -4

